

Inspection Photos
Operator: BP America
API#: 067-09503
Date: 5/20/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing on the slope with grasses such as western wheatgrass and smooth brome.



Photo 3. View of the eastern fill slope facing northward.



Photo 6. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, muttongrass, and penstemon.