

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/22/2020

Submitted Date:

05/22/2020

Document Number:

700700760**FIELD INSPECTION FORM**

Loc ID 335037	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>21</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298254	WELL	PR	12/20/2009	GW	045-17099	FEDERAL SR 43-9	PR
298255	WELL	PR	12/08/2011	GW	045-17100	Federal SR 532-9	PR
298256	WELL	PR	03/02/2009	GW	045-17101	FEDERAL SR 33-9	PR
298257	WELL	PR	12/20/2009	GW	045-17102	FEDERAL SR 11-15	PR
298258	WELL	PR	04/16/2011	GW	045-17103	FEDERAL SR 343-9	PR
419569	WELL	PR	08/30/2011	GW	045-19981	Federal SR 434-9	PR
419572	WELL	PR	10/01/2011	GW	045-19984	Federal SR 334-9	PR
419574	WELL	PR	03/01/2012	GW	045-19985	Federal SR 543-9	PR
419576	WELL	PR	12/26/2011	GW	045-19987	Federal SR 544-9	PR
419580	WELL	PR	10/01/2011	GW	045-19990	Federal SR 34-9	PR
419583	WELL	PR	03/01/2012	GW	045-19993	Federal SR 443-9	PR
419585	WELL	PR	12/08/2011	GW	045-19994	Federal SR 44-9	PR
419586	WELL	PR	03/01/2012	GW	045-19995	Federal SR 344-9	PR
419590	WELL	PR	03/01/2012	GW	045-19998	Federal SR 444-9	PR
419603	WELL	PR	03/01/2012	GW	045-20000	Federal SR 333-9	PR
419604	WELL	PR	12/08/2011	GW	045-20001	Federal SR 433-9	PR
419605	WELL	PR	10/01/2011	GW	045-20002	Federal SR 534-9	PR

General Comment:

COGCC Inspection Report Summary

On Friday 5/22/20 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP SR 33-9, at Location # 335037 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:

	Type Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

	Type CONTAINERS		
Comment:			
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
	Type BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume			
------	------	--------	--	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
	Type TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	chemical tanks at well heads		
Corrective Action:			Date:
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	80 bbl tank					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		
	Date:	

Inspected Facilities									
Facility ID:	298254	Type:	WELL	API Number:	045-17099	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298255	Type:	WELL	API Number:	045-17100	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298256	Type:	WELL	API Number:	045-17101	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298257	Type:	WELL	API Number:	045-17102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298258	Type:	WELL	API Number:	045-17103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419569	Type:	WELL	API Number:	045-19981	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419572	Type:	WELL	API Number:	045-19984	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419574	Type:	WELL	API Number:	045-19985	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	419576	Type:	WELL	API Number:	045-19987	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419580	Type:	WELL	API Number:	045-19990	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419583	Type:	WELL	API Number:	045-19993	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419585	Type:	WELL	API Number:	045-19994	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419586	Type:	WELL	API Number:	045-19995	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419590	Type:	WELL	API Number:	045-19998	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419603	Type:	WELL	API Number:	045-20000	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	419604	Type:	WELL	API Number:	045-20001	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	419605	Type:	WELL	API Number:	045-20002	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Ditches		Ditches				
Berms		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700768	Photos for SR 33-9	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5158003