

# *Inspection Photos*

*Loc#324026*

*Operator: Caerus*

*Inspection Number: 69240200*

*Inspection Date: 5/15/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 15, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Schaffer Loc#324026



Photo#2:  
Interim

May 15, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Interim.

Caerus Schaffer Loc#324026





Photo#4:  
Anchor Marker that needs paint.

May 15, 2020



Photo#5:  
Anchor Marker that needs paint.

Caerus Schaffer Loc#324026