

Inspection Photo

Loc#323979

Operator: Caerus

Inspection Number: 692402219

Inspection Date: 5/15/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

May 15, 2020



Photo#2:
Interim.

Photo#3:
Interim.

May 15, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Pitman Loc#323979



Photo#4:
Marker needing bright paint.



Photo#5:
Going Down Sign.

May 15, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Pitman Loc#323979