

Inspection Photos
Operator: BP America
API#: 067-08678
Date: 5/20/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing on the slope with grasses such as western wheatgrass, James galleta, and intermediate wheatgrass.



Photo 3. View of what appears to be topsoil stockpile within the southeastern project area. Stockpile is weed infested and is not stabilized.



Photo 4. closeup view of dense Russian thistle growing on soil stockpile.



Photo 5. View of musk thistle rosettes within the project area. Approximately 150 individuals observed.



Photo 6. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, muttongrass, and penstemon.