

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2020

Submitted Date:

05/26/2020

Document Number:

699801162

**FIELD INSPECTION FORM**
 Loc ID 334453 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290703	WELL	PR	05/23/2007	GW	077-09298	VEGA UNIT 10-334	PR
290704	WELL	PR	05/23/2007	GW	077-09297	VEGA UNIT 10-234	PR
290705	WELL	PR	05/23/2007	GW	077-09296	VEGA UNIT 10-434	PR
290706	WELL	PR	05/23/2007	GW	077-09295	VEGA UNIT 10-431	PR
292279	WELL	PR	09/17/2007	GW	077-09391	VEGA FEDERAL 10-344	PR
292280	WELL	PR	09/17/2007	GW	077-09390	VEGA FEDERAL 10-241	PR
292281	WELL	PR	09/17/2007	GW	077-09389	VEGA FEDERAL 10-444	PR
292282	WELL	PR	09/23/2009	GW	077-09388	VEGA FEDERAL 10-441	PR
292283	WELL	PR	09/17/2007	GW	077-09387	VEGA FEDERAL 10-341	PR
292284	WELL	PR	09/17/2007	GW	077-09386	VEGA FEDERAL 10-244	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Tuesday 5/26/20 at approximately 12:30 hours, I, Inspector Corey De Paolo,  
 Conducted an on-site inspection at LARAMIE ENERGY LLC Vega /6 Pad,  
 Location #334453 in Mesa County Colorado.  
 While there, I observed normal production operations.  
 This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 8		corrective date
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:	500 gallon capacity				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		Separate containment						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
CONDENSATE	1	400 BBLS	STEEL AST		,			
Comment:								
Corrective Action:							Date:	
<u>Paint</u>								
Condition	Adequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
<u>Berms</u>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate				
Comment:		Centralized containment						
Corrective Action:							Date:	
<u>Venting:</u>								
Yes/No	NO							
Comment:								
Corrective Action:							Date:	
<u>Flaring:</u>								
Type								
Comment:								
Corrective Action:							Date:	

Inspected Facilities									
Facility ID:	290703	Type:	WELL	API Number:	077-09298	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	290704	Type:	WELL	API Number:	077-09297	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	290705	Type:	WELL	API Number:	077-09296	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	290706	Type:	WELL	API Number:	077-09295	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292279	Type:	WELL	API Number:	077-09391	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292280	Type:	WELL	API Number:	077-09390	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292281	Type:	WELL	API Number:	077-09389	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292282	Type:	WELL	API Number:	077-09388	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	292283	Type:	WELL	API Number:	077-09387	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID:	292284	Type:	WELL	API Number:	077-09386	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Compaction				
		Gravel				
		Culverts				
Berms						
Gravel						
		Ditches				
Compaction						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801163	Photos for Insp. #699801162	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159343">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159343</a>