



40.04601, -108.93599, 5190.0ft, 322°
05/26/2020 11:58:27 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Taiga Mtn 16-22-1N-103 API: 05-103-08999
Inspection: 700401672







40.04621, -108.93611, 5192.4ft, 40°
05/26/2020 10:23:20 AM



40.0462, -108.93609, 5179.6ft, 50°
05/26/2020 11:59:06 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Casing valve gas leak.

Taiga Mtn 16-22-1N-103 API: 05-103-08999
Inspection: 700401672