

# Final Reclamation and Stormwater Inspection

May 26, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 317847

Inspection Document #: 697501546

Weld County, CO

SWSW Section 33 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CARL A MILLER UNIT C #1  
Location ID: 317847



**Photo 1.** Photo taken from the well location, facing South. Photo illustrates the well location is reflective of reference crop areas. The well location was just on the east-side of the crop area which is a sufficient representation of the well location crop growth.

Inspection Photos  
Location Name: CARL A MILLER UNIT C #1  
Location ID: 317847



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: CARL A MILLER UNIT C #1  
Location ID: 317847



**Photo 3.** Photo taken from the well location, facing North. Photo illustrates the well location access road is reflective of reference crop areas.

Inspection Photos  
Location Name: CARL A MILLER UNIT C #1  
Location ID: 317847



**Photo 4.** Photo taken from the eastern associated offsite tank battery location, facing West. Photo illustrates the tank battery location is bare without crop growth.

Inspection Photos  
Location Name: CARL A MILLER UNIT C #1  
Location ID: 317847



**Photo 5.** Photo taken from the western associated offsite tank battery location, facing East. Photo illustrates the tank battery location is bare without crop growth.