

Final Reclamation and Stormwater Inspection

May 26, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 319019

Inspection Document #: 697501550

Weld County, CO

CSE Section 32 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HALEY-GUMESON #2
Location ID: 319019



Photo 1. Photo taken from the associated offsite tank battery, facing South. Photo illustrates equipment remains at location.

Inspection Photos
Location Name: HALEY-GUMESON #2
Location ID: 319019



Photo 2. Photo taken from the associated offsite tank battery, facing East. See comments under Photo 1.