

Final Reclamation Inspection

May 26, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 317714

Inspection Document #: 697501552

Weld County, CO

NESE Section 32 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HALEY #1
Location ID: 317714



Photo 1. Photo taken from the well/tank battery location, facing South. Photo illustrates equipment remains at location. This appeared to be a shared battery with Crestone Peak and a corrective action has been submitted to Crestone Peak.