

Final Reclamation Inspection

May 26, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 318492

Inspection Document #: 697501554

Weld County, CO

SENW Section 32 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Rocky Mtn Fuel Co 22-32 battery

Location ID: 318492



Photo 1. Photo taken from the tank battery location, facing West. Photo illustrates equipment remains at location.

Inspection Photos

Location Name: Rocky Mtn Fuel Co 22-32 battery

Location ID: 318492



Photo 2. Photo taken from the western tank battery location, facing North. Photo illustrates cheatgrass in the foreground with the establishment of western wheatgrass in the background.

Inspection Photos

Location Name: Rocky Mtn Fuel Co 22-32 battery

Location ID: 318492



05.26.2020 13:14

Photo 3. Photo taken from the western tank battery location, facing East. See comments under Photo 2.

Inspection Photos

Location Name: Rocky Mtn Fuel Co 22-32 battery

Location ID: 318492



Photo 4. Photo taken from the northwestern tank battery location, facing Northeast. Photo illustrates the establishment of western wheatgrass.

Inspection Photos

Location Name: Rocky Mtn Fuel Co 22-32 battery

Location ID: 318492



Photo 5. Photo taken from the northern tank battery location, facing Northwest. Photo illustrates a List B Colorado noxious weed, Musk thistle. Musk thistle rosettes were observed; there were no shoots observed.