

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #1263 from NW corner of location.



Photo #0815 from inspection #699800778 conducted on 3/24/20.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #1264 Unused pipe stored on North end of location.



Unused equipment by wellhead.