

# Inspection Photos

API: 061-06366

Operator: SAMSON OIL COMPANY

Inspection Date: 5/26/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06366 | Date: 5/26/2020

## Inspection Photos



**Photo 1.** Facing south toward the location. There has been recent reclamation work performed and the location and a fence appears to be installed.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 5/26/2020

## Inspection Photos



**Photo 2.** The bare area of the location appears to have been decompacted and seeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 5/26/2020

## Inspection Photos



**Photo 3.** Facing back toward the north at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 5/26/2020