

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2020

Submitted Date:

05/28/2020

Document Number:

679602756

FIELD INSPECTION FORM

Loc ID 310391 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
,		dnr_cogccengineering@state. co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292394	WELL	SI	09/01/2017	GW	123-26341	WIEST J 28-25	SI

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: Panel		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:					
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292394 Type: WELL API Number: 123-26341 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; No current MIT on record or delinquent as required by Rule 326

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. Date: 06/28/2020

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Thursday, May 28, 2020 at approximately 11:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at WIEST J 28-25 (Noble Energy), at location #: 310391 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. According to production records, wellhead has been shut in since OCTOBER 2016. No current documentation of MIT in well file. Noble has a variance for long term shut-in/temporarily abandon wells and this well (WIEST J 28-25) is not on the list. Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. (Corrective Action Date: June 28, 2020) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	05/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602757	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160696