

Final Reclamation Inspection

May 26, 2020

Operator: MACHII-ROSS PETROLEUM CO - 52250

Location ID: 406103

Inspection Document #: 697501564

Weld County, CO

SWSE Section 32 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HALEY #2
Location ID: 406103



Photo 1. Photo taken from the well location, facing South. Photo illustrates the Operator has failed to remove all equipment.

Inspection Photos
Location Name: HALEY #2
Location ID: 406103



Photo 2. Photo taken from the well location, facing Northwest. Photo illustrates other areas surrounding the well location appear to meet Rule 1004 vegetative standards.

Inspection Photos
Location Name: HALEY #2
Location ID: 406103



Photo 3. Photo taken from the well location, facing Northeast. See comments under Photo 2.

Inspection Photos
Location Name: HALEY #2
Location ID: 406103



Photo 4. Photo taken from the well location, facing South. Photo illustrates the access road appears reflective of reference crop areas.