

Final Reclamation and Stormwater Inspection

May 26, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 319482

Inspection Document #: 697501570

Weld County, CO

CSW Section 32 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ROCKY MOUNTAIN FUEL CO #4-32J
Location ID: 319482



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates the access point is still be used to access monitoring wells for an active remediation project. Operator will be responsible for reclaiming all disturbance areas.

Inspection Photos
Location Name: ROCKY MOUNTAIN FUEL CO #4-32J
Location ID: 319482



Photo 2. Photo taken from the central location, facing East. Photo illustrates Operator has performed final reclamation activities with the evidence of straw crimped mulch and some germination.

Inspection Photos
Location Name: ROCKY MOUNTAIN FUEL CO #4-32J
Location ID: 319482



Photo 3. Photo taken from the central location, facing North. Photo illustrates some of the monitoring wells which are located along the northern location.

Inspection Photos
Location Name: ROCKY MOUNTAIN FUEL CO #4-32J
Location ID: 319482



Photo 4. Photo taken from the central location, facing East. Photo illustrates little to no germination throughout large portions of the location. Operator will likely have to perform additional reclamation activities.

Inspection Photos
Location Name: ROCKY MOUNTAIN FUEL CO #4-32J
Location ID: 319482



Photo 5. Photo taken from the northwestern location, facing North. Photo illustrates stormwater BMPs that appear to be decommissioned. Operator shall remove all unused materials if no longer needed.