

Transect Data Collection

Pad Site:

Dupont Lake 4318


Transect Locations:

Date/Time:

5-27-2020
1411

Inspectors:

J Valdez swiseman
J Valdez
Guard



Representative Area

Reclamation Area

Notes:

Start Coord:

37.43263, 104.59588

Start Coord:

37.43217, 104.59630

Point	Hit	Miss	Point	Hit	Miss
1		X	1		X
2	X		2	X	
3		X	3	X	
4		X	4		X
5		X	5		X
6		X	6	X	
7	X		7		X
8	X		8		X
9		X	9		X
10	X		10		X
11		X	11		X
12	X		12		X
13		X	13		X
14		X	14	X	
15	X		15		X
16	X		16	X	
17		X	17		X
18		X	18		X
19	X		19		X
20	X		20	X	
21		X	21	X	
22	X	X	22	X	X
23		X	23	BUSH	
24		X	24		X
25		X	25		X
Total	10		Total	7	

End Coord:

37.43254, 104.59597


End Coord:

37.43210, 104.59646

Percentage: REC/REP

40%

28%



This map has been produced by Pioneer Natural Resources. This map may contain data supplied under licence to Pioneer Natural Resources. Whilst every effort has been made to ensure the information contained in the map is up-to-date and accurate, Pioneer Natural Resources accepts no responsibilities if the map is not complete and/or contains inaccuracies. Use of this information is at your sole risk and if you rely on the information you are responsible for

Dupont Lake 43-18 Transect
Vegetative Assessment Locations