

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2020

Submitted Date:

05/29/2020

Document Number:

700900108

**FIELD INSPECTION FORM**

Loc ID 320421 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1001 17TH STREET #2000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone        | Email                       | Comment                         |
|---------------|--------------|-----------------------------|---------------------------------|
| Musgrave, Tim | 970-768-6097 | cogccinspections@gwogco.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 203722      | WELL | TA     | 12/01/2019  | OW         | 001-09282 | CAVALIER 2-3N4 | TA          |

**General Comment:**

*(This area is intentionally left blank for general comments.)*

| Location   |                      |        |                 |
|--|----------------------|--------|-----------------|
| <b>Lease Road:</b>                                     |                      |        |                 |
| Type   | Access               |        |                 |
| comment:   | Adequate             |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |                      |        |                 |
| <b>Signs/Marker:</b>                                   |                      |        |                 |
| Type   | WELLHEAD             |        |                 |
| Comment:   | Adequate             |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| Type   | TANK LABELS/PLACARDS |        |                 |
| Comment:   | Adequate             |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| Emergency Contact Number:                              |                      |        |                 |
| Comment:   | Adequate             |        |                 |
| Corrective Action:                                     |                      |        | Date: _____     |
| Overall Good: <input checked="" type="checkbox"/>      |                      |        |                 |
| <b>Spills:</b>   |                      |        |                 |
| Type   | Area                 | Volume |                 |
| In Containment: No                                     |                      |        |                 |
| Comment:   |                      |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |                      |        |                 |
| <b>Fencing/:</b>                                       |                      |        |                 |
| Type   | WELLHEAD             |        |                 |
| Comment:   | Chain link           |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| <b>Equipment:</b>                                      |                      |        | corrective date |
| Type: Gas Meter Run                                    | # 1                  |        |                 |
| Comment:   |                      |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| Type: Bird Protectors                                  | # 2                  |        |                 |
| Comment:   |                      |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| Type: Deadman # & Marked                               | # 4                  |        |                 |
| Comment:   |                      |        |                 |
| Corrective Action:                                     |                      |        | Date:           |
| Type: Pump Jack  | # 1                  |        |                 |
| Comment:   |                      |        |                 |
| Corrective Action:                                     |                      |        | Date:           |

|                                   |                                  |  |       |
|-----------------------------------|----------------------------------|--|-------|
| Type: Emission Control Device     | # 1                              |  |       |
| Comment:                          |                                  |  |       |
| Corrective Action:                |                                  |  | Date: |
| Type: Horizontal Heated Separator | # 1                              |  |       |
| Comment:                          |                                  |  |       |
| Corrective Action:                |                                  |  | Date: |
| Type: Bradenhead                  | # 1                              |  |       |
| Comment:                          | Appears to be plumbed to surface |  |       |
| Corrective Action:                |                                  |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 39.910296,-104.526481 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLs | FIBERGLASS AST |         |        |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                    | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------|---------------------|---------------------|-------------|
| Earth              | Adequate                    | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | Shares berm with crude tank |                     |                     |             |
| Corrective Action: |                             |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 203722 Type: WELL API Number: 001-09282 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

| Comment                            | User     | Date       |
|------------------------------------|----------|------------|
| <a href="#">Routine inspection</a> | finkenbc | 05/29/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700900109    | Inspectine photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5161820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5161820</a> |