



## Inspection Photos

Location Name: CAERUS PICEANCE LLC NAUROTH-68S96W /2SENE

Location ID: 334160



**Photo #1278 from NW corner of location**



**Photo #1279 Chemical tank labels weathered and not legible.**