



39.92465, -108.74121, 5711.5ft, 47°
05/27/2020 04:57:29 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Fork Unit 3-33-1-1

API: 05-103-08463

Inspection: 700401700



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Fork Unit 3-33-1-1

API: 05-103-08463

Inspection: 700401700



39.92469, -108.74082, 5710.5ft, 41°
05/27/2020 04:56:10 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Meter building.

Fork Unit 3-33-1-1

API: 05-103-08463

Inspection: 700401700