

Inspection Photos
Location Name: Dita (JDitirro) 1
Location ID: 318141



Photo 1 PA wellsite facing East

Photo 2 PA wellsite facing South West

Inspection Photos
Location Name: Dita (JDitirro) 1
Location ID: 318141



Photo 3 gas meter run

Photo 4 Horizontal Heated Separator

Inspection Photos
Location Name: Dita (JDitirro) 1
Location ID: 318141




Photo 5 TB

Photo 6 TB missing sign no operator information, emergency number

Inspection Photos
Location Name: Dita (JDitirro) 1
Location ID: 318141



Photo 7 load line drip barrel laying in its side

Photo 8 load line drip barrel laying in its side