

Inspection Photos  
Operator: Highpoint Operating  
API#: 033-06146  
Date: 5/27/2020



Photo 1. View of sparse revegetation within the northeastern project area. Revegetation is comprised of mixed grasses such as crested wheatgrass and western wheatgrass.



Photo 2. View of sparse revegetation within the southeastern project area. Scattered alfalfa are significantly more sparse and smaller than surrounding cropfield.





Photo 3. View of the central well pad from the southwestern corner facing center. Revegetation is progressing here.





Photo 4. View of the southwestern fill slope facing southeastward. Revegetation is progressing on the fill slope.





Photo 5. View of reference area vegetation comprised of rabbitbrush and sagebrush shrublands with understory of seeded grasses such as smooth brome and crested wheatgrass.