

Inspection Photos

5/26/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 422990

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 422990



Photo 1: Photo taken from the northern corner of the Location, facing southeast. Photos 1-2 provide an overview of the Location from southeast to southwest.

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 422990



Photo 3: Photo taken from the cut slopes on the northern end of the Location. Photo shows a seep appears to have developed in the cut slope resulting in water discharging and erosion degradation.



Photo 4: Continued from photo 3. Photo shows erosion degradation/sediment deposition on the pad from the cut slope

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 422990



Photo 5: Photo taken from the perimeter stormwater diversion ditch on the north end of the Location. Photo shows Canada thistle rosettes; This is a Colorado State listed noxious weed and requires management.