

# Inspection Photos

5/26/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 414132

Gunnison County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, north to east. Photo shows interim reclamation appears to have been conducted, however areas remain on the current pad that do not appear to be needed for production.

**Photo 2:** See comments under photo 1.

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 414132



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo taken from the southwest end of the Location, facing southwest. Photo shows area where perimeter stormwater diversion ditch discharges from the Location; BMP has not been constructed in accordance with good engineering practices, or with a sufficient stabilized outlet to prevent degradation, and allow for sediment laden-free stormwater discharge from the Location; Erosion degradation evident with off-site sediment transport and deposition occurring

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 414132



**Photo 5:** Photo taken from the southwest end of the Location, facing south. Photo shows stormwater erosion and off-site sediment transport and deposition occurring



**Photo 6:** Photo taken from the southwest end of the Location, facing north. Photo shows area where perimeter stormwater diversion ditch discharges from the Location; BMP has not been constructed in accordance with good engineering practices, or with a sufficient stabilized outlet to prevent degradation, and allow for sediment laden-free stormwater discharge from the Location; Erosion degradation evident with off-site sediment transport and deposition occurring