

Final Reclamation Inspection

May 29, 2020

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 332567

Inspection Document #: 697501573

Weld County, CO

NWSE Section 22 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TUSCANY #10-22-24
Location ID: 332567



Photo 1. Photo taken from the location, facing South. Photo illustrates only one well has been drilled at location.