

Inspection Photos
Location Name: DILLARD AB /10-08
Location #: 416754



Photo #1

Dillard AB 10-08 (05-123-31485) Wellsite

Shut-In | SI



Photo #2

Dillard AB 10-08, Jeanie AB10-01R Battery site

Inactive | Shut-down

Inspection Photos
Location Name: DILLARD AB /10-08
Location #: 416754



Photo #3
Dillard AB 10-08 Wellsite
Faded Container labels
prior insp.



Photo #4
Dillard AB 10-08 Wellsite
Faded Container labels
Faintly legible : Consider replacing