

Inspection Photos

ID: 262144

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 262144 | Date: 5/29/2020

Inspection Photos



Photo 1. The open excavation disturbance has been closed and reclaimed since the previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 5/29/2020

Inspection Photos



Photo 2. Facing north toward the pit and disturbance area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 5/29/2020

Inspection Photos



Photo 3. Facing northeast toward the offsite pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 5/29/2020