

Inspection Photos

API: 071-06565

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/29/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06565 | Date: 5/29/2020

Inspection Photos



Photo 1. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06565 | Date: 5/29/2020

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06565 | Date: 5/29/2020

Inspection Photos



Photo 3. Facing northwest across the road from the location. A berm with rock rip/rap has been installed. Disturbed soils were seeded and tracked.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06565 | Date: 5/29/2020

Inspection Photos



Photo 4. Facing northwest toward the pit. The disturbed soils have been seeded and temporarily stabilized by tracking.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06565 | Date: 5/29/2020

Inspection Photos



Photo 5. Facing toward the pit which is northeast of the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06565 | Date: 5/29/2020