

Inspection Photos  
Operator Name: Caerus Piceance LLC  
Location: 324114



Temporary abandoned well




Wellhead

Inspection Photos  
Operator Name: Caerus Piceance LLC  
Location: 324114



A new 2" Stainless steel flow line will be installed from separator to gas meter, Approximately 20'



Dead leg riser flowline to be removed