

Inspection Photos

API: 071-06574

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06574 | Date: 5/29/2020

Inspection Photos



Photo 1. Facing west along the main road near the location. The road is stabilized and BMP's are installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06574 | Date: 5/29/2020

Inspection Photos



Photo 2. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06574 | Date: 5/29/2020

Inspection Photos



Photo 3. Facing north. Vegetation is well established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06574 | Date: 5/29/2020

Inspection Photos



Photo 4. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06574 | Date: 5/29/2020