

Final Reclamation Inspection

May 29, 2020

Operator: MARKUS PRODUCTION, INC - 53790

API #: 05-123-11156

Inspection Document #: 697501577

Weld County, CO

NENE Section 22 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: WEBSTER #41-22

API #: 05-123-11156




Photo 1. Google Earth aerial imagery taken 10/3/1999. Imagery shows the well location (123-11156) and the associated offsite tank battery (upper left corner). Both the well and associated offsite tank battery location are within a final land use change. Refer to the following aerial imagery of the current, final land use change.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697501577

Inspection Photos
Location Name: WEBSTER #41-22
API #: 05-123-11156



Photo 2. Google Earth aerial imagery taken 7/17/2019. Both the well (Greeley Shopping Center) and associated offsite tank battery (Spradley Barr Ford parking lot) location are within a final land use change.

Inspection Photos
Location Name: WEBSTER #41-22
API #: 05-123-11156



Photo 3. Photo taken from the well location, facing East. Photo illustrates the well location is within the Greeley Shopping Center.

Inspection Photos
Location Name: WEBSTER #41-22
API #: 05-123-11156



Photo 4. Photo taken from the associated offsite tank battery location, facing East. Photo illustrates the tank battery is within a Spradley Barr Ford parking lot.

Inspection Photos
Location Name: WEBSTER #41-22
API #: 05-123-11156



Photo 5. Photo taken from the associated offsite tank battery location, facing West.
See comments under Photo 4.