

# *Inspection Photos*

*Loc#314168*

*Operator: RMNG/Blk Hills*

*Inspection #: 692402225*

*Inspection Date: 5/28/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168





Photo#2:  
BMPs.



Photo#3:  
BMPs.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168





**Photo#4:**  
Views along access road and entry into Location.



**Photo#5:**  
Views along access road and entry into Location.

May 28, 2020



Photo#6:  
Cracking /sloughing at entry.

May 28, 2020



Photo#7:  
Cracking /sloughing at entry.





Photo#8:  
Stained soil/gravel in areas of location.



Photo#9:  
Stained soil/gravel in areas of location.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168



Photo#10:  
Cellars over flowing with stormwater.

Photo#11:  
Cellars over flowing with stormwater.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168





Photo#12:  
Open Cellars measure 4 ft deep.

May 28, 2020



Photo#13:  
Open Cellars measure 4 ft deep.





Photo#14:  
Various trash/debris.

Photo#15:  
Various trash/debris.

May 28, 2020





Photo#16:  
Improperly stored/unused equipment, supplies

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#17:  
One of several rebar protruding from pad surface



Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168