

Smith Energy LLC, Hickert 24-9349
121-10794

Inspection #688307918

5/27/2020

Routine Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.80244, -102.86981, 4347.1ft, 306°
05/27/2020 02:11:00 PM



Colorado Oil and Gas Conservation Commission
39.80253, -102.86986, 4307.7ft, 192°
05/27/2020 02:10:25 PM



Bird cover needs to be completely closed, NFPA sign for produced water has to have at least 1 for dissolved gas, and maintain tank labels for quantity and contents.

Colorado Oil and Gas Conservation Commission
39.80246, -102.86994, 4343.8ft, 251°
05/27/2020 02:11:17 PM



Colorado Oil and Gas Conservation Commission
39.80247, -102.87009, 4334.0ft, 249°
05/27/2020 02:11:34 PM



Colorado Oil and Gas Conservation Commission
39.80276, -102.8701, 4353.7ft, 292°
05/27/2020 02:12:59 PM



Colorado Oil and Gas Conservation Commission
39.80276, -102.87014, 4360.2ft, 26°
05/27/2020 02:13:16 PM