

Inspection Photos

Location Name: CAERUS PICEANCE LLC KNOX-68S96W /14SENW

Location ID: 334083



Photo #1280 from entrance to location



Photo #0874 from inspection #699800814 conducted on 3/30/20.

Inspection Photos

Location Name: CAERUS PICEANCE LLC KNOX-68S96W /14SENW

Location ID: 334083



Photo #1281 Tank by pig station not properly labeled.



Photo #1282 Oily fluid in containment by pigging station.