

Inspection Photos  
Location Name: Antelope Farms 1-24  
Location ID: 320098



Photo #1 tank.



Photo #2 separator and meter run.

# Inspection Photos

Location Name: Antelope Farms 1-24

Location ID: 320098



Station #	Ad	Gr	Station Name	Sec	TwnShip	Range
36244	137	55	ANTELOPE FARMS #1-24	24	25	63W
Radio #	Producer Name		HAINES RICH			
840-3868						
Transmitter / Module #	Federal #	State #	Mtr Tube Size 3.063			
6330087/0270	039/11/11	21	County ADAMS			
			State COLO			
			Meter # 3-81-19266			
Static / Span	Up / Down	Diff / Span	Temp / Span	Absolute	API #	
7-300"		0-250"	0-150°	12.24		
Test Date	OP Size	Beta	Sample Date	H <sub>2</sub> S	Sample Date	H <sub>2</sub> S
7-21-10	1.500		6-25-10	4ppm		
8-28-11	1.500		6-28-11	4ppm		
1-15-12	1.500 n/w		7-3-12	4ppm		77 SP 99 TA
2-24-13	.75 Producer Reg					
3-6-13	.625 P16					
5-5-13	.625 V		6-5-13	1.0ppm		55pp 604p
9-9-14	.625					
1-16-15	.625 V		No Flow			
5-28-16	.625 V		UPGA			
10-15-17	.625 V		UPGA			
1-20-18	.625		UPGA GAS SAMPLE			
1-18-18	.625		UPGA			

May 28, 2020 at 9:49:57 AM  
N 39° 51' 35", W 104° 23' 37"  
249° V  
Adams County Inspection

Photo #3 Produced water pit.

Photo #4 meter calibration card.



**Inspection Photos**  
**Location Name: Antelope Farms 1-24**  
**Location ID: 320098**



**Photo #5 well head**