

Inspection Photos
Location Name:Kallsen AC 15-1
Location ID: 320358



Photo#1 Production tank and produced water pit

Photo#2 Separator and ECD

Inspection Photos
Location Name:Kallsen AC 15-1
Location ID: 320358



Photo#3 Wellhead/Pumpjack

Corrective Action:Guard missing on unit