

Inspection Photos
Location Name: Nichols Well#1
Location ID: 320127




Photo#1 Production tank and Produced water pit



Photo#2 **Corrective Action: No label showing amount tank holds.**

Inspection Photos
Location Name: Nichols Well#1
Location ID: 320127



Photo#3 Separator/ECD/(2) Propane tanks

Corrective Action: Debris all around location

Photo#4 Wellhead