

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2020

Submitted Date:

06/02/2020

Document Number:

696103046**FIELD INSPECTION FORM**Loc ID 330538 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251454	WELL	SI	03/01/2020	OW	123-19257	SLW GREEN STATE BB 18-09	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Active.

Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358).
(Well(s): 1: Producing | PR ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type			
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.396340,-104.478730
Comment:	Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing PR ; 2: Shut-In SI ; 2: Temporarily Abandoned TA). Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	251454	Type:	WELL	API Number:	123-19257	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In SI. Observed production valves shut. COGCC records indicate last production: 02/2020.</div>							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 06/02/2020 at approximately 15:42 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SLW GREEN STATE-65N63W /18NESE Location ID: 30538 Well Name: SLW Green State BB 18-09 API: 05-123-19257 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing PR ; 2: Shut-In SI ; 2: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103047	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164917