

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2020

Submitted Date:

06/02/2020

Document Number:

696103050

FIELD INSPECTION FORM

Loc ID 330357 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

19 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251159	WELL	TA	02/01/2017	OW	123-18962	SLW GREEN STATE BB 18-11	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Active.

Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358).
(Well(s): 1: Producing | PR ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Please remove unused well parts at wellsite. See photo #1.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Temporarily Abandoned TA. Equipment assigned to Location #428198.		

Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned TA. Equipment removed		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead w/ master & casing valves		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Temporarily Abandoned TA. Equipment assigned to Location #428198.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Temporarily Abandoned TA. Equipment assigned to Location #428198.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.396340,-104.478730
Comment:	Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing PR ; 2: Shut-In SI ; 2: Temporarily Abandoned TA). Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:	Temporarily Abandoned TA. Equipment assigned to Location #428198.				
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment:				Temporarily Abandoned TA. Equipment assigned to Location #428198.	
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 251159 Type: WELL API Number: 123-18962 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Well disconnected from flowline.
Yellow LTSI tag posted at well.
Locked-Out, Tagged-Out | LOTO.
COGCC records indicate last production: 04/2015.
SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program).
Doc #02385001 (NOBLE).
Form 4 Sundry doc. #402079635 indicates Temporarily Abandoned | TA status: 04/13/2015.
Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 06/02/2020 at approximately 15:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SLW GREEN STATE BB65N63W /18NESW Location ID: 330357 Well Name: SLW Green State BB 18-11 API: 05-123-18962 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Active.</p> <p>Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing PR ; 2: Shut-In SI ; 2: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.</p> <p>Good Housekeeping Comment: Please remove unused well parts at wellsite. See photo #1.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/02/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103051	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164919