

<b>Well Name:</b>	Ute T 2	<b>API #</b>	067-8785
<b>Well Name:</b>	IGE 114	<b>API #</b>	067-09389
<b>Well Name:</b>	IGE 118	<b>API #</b>	067-09560
<b>Inspection Number:</b>	693901617		
<b>Corrective Action:</b>	Scattered musk thistles observed throughout the interim reclamation area. Control weeds at the appropriate time and before flowering in 2020.		
<b>Action Completed:</b>	Spray weeds to control spread.		
<b>Action Taken:</b>	5/8/2020		

