

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /20-03 Pad

Location ID: 449070



Photo #1297 from entrance to location



Photo #1300 Multiple places with unused equipment on location.



## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /20-03 Pad

Location ID: 449070



**Photo #1301 Multiple places with unused equipment on location.**



**Photo #1298 Berm has eroded and migrated into adjacent ditch.**