

Inspection Photos
Location Name: Motis 1-6
Location ID: 329265



Photo 1 – Wellhead – Weeds actively growing and Fencing is in disrepair



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Motis 1-6
Location ID: 329265



Photo 3 – All Production Equipment removed



Photo 2 – Gas Meter remains on Location