

Inspection Photos
Location Name: Pergamos 4-44-7-60 PAD
Location ID: 423984



Photo 1 – Pumping Units, unused Tubing



Photo 2 – Tank Battery

Inspection Photos
Location Name: Pergamos 4-44-7-60 PAD
Location ID: 423984



Photo 3 – Stained Soil at Engine Exhaust



Photo 4 – Stained Soil at East Loadout

Inspection Photos
Location Name: Pergamos 4-44-7-60 PAD
Location ID: 423984



Photo 5 – Unused Rods at the Southside of Location