

# Final Reclamation Inspection

June 2, 2020

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-07899

Inspection Document #: 697501597

Weld County, CO

SWNW Section 23 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the western location, facing East. Operator has performed final reclamation activities with the evidence of reference area grass species (Cereal rye). The establishment of Cereal rye does not appear to be reflective of reference areas; therefore, this location will remain in-process.



Inspection Photos  
Location Name: KNOX #1-23  
API: 05-123-07899



**Photo 2.** Photo taken from the western location, facing South. See comments under Photo 1.





**Photo 3.** Photo taken from the western location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: KNOX #1-23  
API: 05-123-07899



**Photo 4.** Photo taken from the western location, facing West. See comments under Photo 1. Photo also illustrates a List B Colorado noxious weed, Scotch thistle (red circle).





**Photo 5.** Close up photo taken of a List B Colorado noxious weed, Scotch thistle.





**Photo 6.** Photo taken from the southwestern location, facing South. Photo also illustrates a patch of List B Colorado noxious weeds, Scotch thistle (red circle).





**Photo 7.** Reference photo taken west of the location, facing West. Photo illustrates the location is not reflective of reference area vegetative levels; therefore, will remain in-process.