

Inspection Photos

Loc#334361

Operator: Caerus

Inspection Number: 692402236

Inspection Date: 5/26/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

May 26, 2020



Photo#2:
Erosion tunneling.

May 26, 2020



Photo#3:
Erosion tunneling.



Photo#4:
Daylighting and subsidence further down the fill slope.



Photo#5:
Daylighting and subsidence further down the fill slope.

May 26, 2020