

Inspection Photos

6/03/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 315237

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315237



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Photo shows equipment and debris has been removed from the Location. Photo also shows no additional reclamation activities appear to have been conducted pursuant to Rule 1004.a and corrective actions.

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315237



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315237



Photo 5: Photo taken from areas where the tanks existed. Photo shows stained soils remain on the location.



Photo 6: Photo taken from areas where the tanks existed, facing west. Photo shows stained soils remain on the location.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315237



Photo 7: Photo taken from the west side of the pit, facing east. Photo shows pit has not been closed; Pit closure in process.



Photo 8: Photo taken from the south end of the Location, facing east. Photo shows no additional reclamation activities appear to have been conducted pursuant to Rule 1004.a and corrective actions, including by not limited recontouring.