

Inspection Photos

6/03/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 398846

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 1: Photo taken from the east end of the Location, facing southwest. Photo provides an overview of the Location. Photo shows Operator has not installed additional BMPs to be used in conjunction with tracking; Tracking is a temporary control and will not be sufficient for long term stabilization until vegetation has established; Tracking should be used in conjunction with other BMPs per good engineering practices.



Photo 2: Photo taken from the east end of the Location, facing northwest. See comments under photo 1.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 3: Photo taken from the east end of the Location. Photo shows cable debris remaining on the Location.



Photo 4: Photo taken from the east end of the Location. Photo shows what appears to be a cable anchor remaining on the Location.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 398846



Photo 5: Photo taken from the southwestern area of the Location. Photo shows pipe debris has not been removed from the Location.



Photo 6: Photo taken from the access road. Photo shows access road has not been reclaimed in accordance with COGCC 1004 rules.