

Inspection Photos  
Location Name: Sunflower 24N-17HZ TB  
Location ID: 442961



Photo 1 TB signs

Photo 2 TB

**Inspection Photos**  
**Location Name: Sunflower 24N-17HZ TB**  
**Location ID: 442961**



**Photo 3 LACT**

**Photo 4 ECDs**

**Inspection Photos**  
**Location Name: Sunflower 24N-17HZ TB**  
**Location ID: 442961**



**Photo 5 Horizontal Heated Separators**

**Photo 6 Horizontal Heated Separators**

**Inspection Photos**  
**Location Name: Sunflower 24N-17HZ TB**  
**Location ID: 442961**



**Photo 7 compressor**

**Photo 8 Gas Meter Runs**

# Inspection Photos

## Location Name: Sunflower 24N-17HZ TB

### Location ID: 442961





Photo 9 card inside East meter house

Photo 10 card inside West meter house

**Inspection Photos**  
**Location Name: Sunflower 24N-17HZ TB**  
**Location ID: 442961**



**Photo 11 FWKO**