

Inspection Photos
Location Name: Razor 26I PAD
Location ID: 435160



Photo 1 – Wellheads



Photo 2 – Wellheads

Inspection Photos
Location Name: Razor 26I PAD
Location ID: 435160



Photo 3 – Wellheads




Photo 4 – Razor 26I-2324B missing Wellhead Sign