

Inspection Photos

Location Name: SLW GREEN STATE BB-65N63W /18NESW

Location #: 330357



Photo #1

SLW Green State BB 18-11 (05-123-18962) Wellsite

Temporarily Abandoned | TA

**Unused well parts
prior insp.**



Photo #2

SLW Green State BB 18-11 Wellsite

Temporarily Abandoned | TA

Unused well parts: Removed

Inspection Photos

Location Name: SLW GREEN STATE BB-65N63W /18NESW

Location #: 330357



Photo #3

**Vince State B13-63HN,
SLW Green State BB 18-09, 18-10, 18-11, 18-12**

Battery site

Active
prior insp.